



# TRIMETHOXYSIANE

NA 9269

Shipping Name: Trimethoxysilane



**WARNING!** • **POISON! BREATHING THE VAPORS, SWALLOWING THE MATERIAL OR SKIN CONTACT CAN KILL YOU! SKIN AND EYE CONTACT CAUSES SEVERE BURNS AND BLINDNESS!**

• Firefighting gear (including SCBA) does not provide adequate protection. If exposure occurs, remove and isolate gear immediately and thoroughly decontaminate personnel

## Hazards:

- Highly flammable
- Vapors are heavier than air and will collect and stay in low areas
- Containers may BLEVE when exposed to fire
- Vapors may travel long distances to ignition sources and flashback
- Vapors in confined areas (e.g., tanks, sewers, buildings) may explode when exposed to fire
- May react with itself when heated plugging relief valves causing a violent explosion

## Awareness and Operational Level Training Response:

- **Do not put yourself in danger by entering a contaminated area to rescue a victim**
- Stay upwind and uphill
- Determine the extent of the problem
- Isolate the area of release or fire and deny entry
- Remove all ignition sources
- For container exposed to fire evacuate the area in all directions because of the risk of BLEVE
- Evacuate the immediate area and downwind for a large release
- Notify local health and fire officials and pollution control agencies
- If material or contaminated runoff enters waterways, notify downstream users of potentially contaminated water

## Description:

- Colorless liquid
- Sweet odor
- Floats on water and is insoluble in water but slowly reacts with water forming a corrosive mixture
- Highly flammable
- Vapors are heavier than air and will collect and stay in low areas

## Operational Level Training Response:

### RELEASE, NO FIRE:

- Stop the release if it can be done safely from a distance
- Prevent material and runoff from entering sewers and waterways if it can be done safely well ahead of the release
- Use large amounts of water well away from the material to disperse vapors - contain runoff
- Consider the application of foam to large areas of spilled liquid to control vapors
- Ventilate confined area if it can be done without placing personnel at risk

### FIRE:

- If material is on fire, and conditions permit, **DO NOT EXTINGUISH.**
- Material reacts with water but can be extinguished with medium expansion AFFF alcohol resistant foam
- If material is not leaking, cool exposed containers with large quantities of water from unattended equipment or remove intact containers if it can be done safely
- If cooling streams are ineffective (venting sound increases in volume and pitch, tank discolors or shows any signs of deforming), withdraw immediately to a secure location

## First Aid:

- **Do not put yourself in danger by entering a contaminated area to rescue a victim**
- Provide Basic Life Support/CPR as needed
- Decontaminate the victim as follows:
  - ♦ Inhalation - remove the victim to fresh air and give oxygen if available
  - ♦ Skin - remove and isolate contaminated clothing (including shoes) and wash skin with soap and large volumes of water for 15 minutes
  - ♦ Eye - rinse eyes with large volumes of water or saline for 15 minutes
  - ♦ Swallowed - do not make the victim vomit
- Seek medical attention
- Toxic effects may be delayed
- For skin burns decontaminate with water and apply a clean dry dressing

CAS: 2487-90-3